



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D2362-041
Job Sheet 210056



Part No: D2362-041

Job Qty: 2 pcs

Part Name: AS350/AS355 Pre-Flight Step



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 5/25/20

Job Tracking No:

Due Date: 6/12/20

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG D2362 REV.F IPP C 00.06.26 Removed P/O for powder coat EC IPP REV:D 2020.01.13 AS PER DW
REV.F DD VERF:JFS

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Large Fab - Steps - 1	2 pcs	6/11/20		0.00	1.52	Large Fab - 1		
							Large Fab - 10		
							Large Fab - 2		
							Large Fab - 3		
							Large Fab - 4		
							Large Fab - 5		
							Large Fab - 6		
							Large Fab - 7		
							Large Fab - 8		
							Large Fab - 9		
							Large Fab - 11 (Various)		
							Large Fab - 12		
110	QC 5	2 pcs	6/11/20		0.00	0.00	QC 5 - 10		
							QC 5 - 12		
							QC 5 - 17		
							QC 5 - 18		
							QC 5 - 19		
							QC 5 - 22		
							QC 5 - 24		
							QC 5 - 3		
							QC 5 - 43		
							QC 5 - 49		
							QC 5 - 51		
							QC 5 - 58		
							QC 5 - 68		
							QC 5 - 9		
							QC 5 - 50		
							QC 5 - 30		
							QC 5 - 40		
							QC 5 - 61		



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S282318



Part: D2362-041

Job No: 210056

Serial No/Batch: S282318

Revision: REV.G

Inspector:

Exp Date:

Instructions: Various STC's

Date: 06/10/20

Plex 5/25/20 8:35 AM Dart.lajeunesse.marie

120 QC 9	2 pcs	6/11/20	0.00 0.00	QC 5 - 81	
				QC 5 - 82	
				QC 9 - 10	
				QC 9 - 18	
				QC 9 - 24	
				QC 9 - 43	
				QC 9 - 50	
				QC 9 - 9	
130 Powdercoat - 1 White Gl(A)- B4B	2 pcs	6/11/20	0.00 0.21	Powdercoat - 1 - B4B	
				Powdercoat - 2 - B4B	
				Powdercoat - 3 - B4B	
				Powdercoat - 4 - B4B	
140 QC 3	2 pcs	6/11/20	0.00 0.00	QC 3 - 10	
				QC 3 - 13	
				QC 3 - 15	
				QC 3 - 17	
				QC 3 - 18	
				QC 3 - 2	
				QC 3 - 28	
				QC 3 - 3	
				QC 3 - 30	
				QC 3 - 34	
				QC 3 - 36	
				QC 3 - 41	
				QC 3 - 51	
				QC 3 - 58	
				QC 3 - 59	
				QC 3 - 68	
				QC 3 - 9	
				QC 3 - 40	
				QC 3 - 19	
				QC 3 - 43	
				QC 3 - 24	
				QC 3 - 61	
				QC 3 - 81	
				QC 3 - 82	
				QC 3 - 87	
150 Handfinish - 3-1- WingWalk- B4B	2 pcs	6/12/20	0.00 0.36	Handfinish - 3 - 1 - B4B	
				Handfinish - 3 - 2 - B4B	
				Handfinish - 3 - 3 - B4B	
				Handfinish - 3 - 4 - B4B	
				Handfinish - 3 - 5 - B4B	
160 QC 5	2 pcs	6/12/20	0.00 0.00	QC 5 - 10	
				QC 5 - 12	
				QC 5 - 17	
				QC 5 - 18	
				QC 5 - 19	
				QC 5 - 22	
				QC 5 - 24	
				QC 5 - 3	
				QC 5 - 43	
				QC 5 - 49	
				QC 5 - 51	
				QC 5 - 58	
				QC 5 - 68	
				QC 5 - 9	
				QC 5 - 50	
				QC 5 - 30	
				QC 5 - 40	

170 Packaging 3-1 - Stock - B4B	2 pcs	6/12/20	0.00 0.00	QC 5 - 61	
				QC 5 - 81	
				QC 5 - 82	
				Packaging 3 - 1 - B4B	
				Packaging 3 - 2 - B4B	
				Packaging 3 - 3 - B4B	
				Packaging 3 - 4 - B4B	
				Packaging 3 - 5 - B4B	
180 QC 21 - SA	2 pcs	6/12/20	0.00 0.00	Packaging 3 - 6 - B4B	DAS
				Packaging 3 - 37 - B4B	28
				QC 21 - SA - 21	9-89
				QC 21 - SA - 70	JUN 16 2020
				QC 21 - SA - 9	70

Part Op 100 - Cut D2244 extrusion 3.75" long Deburr D2244-3.75 Weld D2244-3.75 to D2362-7 as per Dwg D2362 and QSI 004
 Descriptions: 110 - QC5- Inspect part completeness to step on W/O

120 - (QC9- Inspect visual per QSI004- Fusion Welds)

130 - (White Gloss (Ref: 4.3.5.1) per QSI005 4.3-Alum) START TIME: 7:20 OVER TEMPERATURE: 300°

FINISH TIME: 7:00

140 - (QC3- Inspect Part Finish)

150 - (Wing Walk as per dwg QSI005 4.4 Batch 526-4-10) Mask bracket and apply black anti-skid paint as per QSI 005 4.4

160 - (QC5- Inspect part completeness to step on W/O)

170 - (Identify as per dwg & Stock Location: _____)

180 - (QC21- Final Inspection - Work Order Release)

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2244-116	Step Extrusion	.0700 pcs (.035 ea)	100-Large Fab - Steps - 1	5210457
D2362-7	Support Bracket	2 pcs (1 ea)	100-Large Fab - Steps - 1	5281854

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Large Fab - Steps - 1	D2244-116	0	49	0
	D2362-7	2	0	0

Part Specifications

Specifications could not be found.

Plex 5/25/20 8:35 AM Dart.lajeunesse.marie

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier Quality ☐		
Date :	Sequence #:	QTY Affected :		MRB (QSI042)
Description Work Order Deviation		Disposition		Completed By
				Lead hand / Supervisor
				QC / QA Coordinator
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Preservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐	FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:				